

DMPOA, Inc.
Road Report 5-13-2017

Worked:

Worked main road, main road. Recovered 65 truck loads of material and about 25% is now screened.

Equipment:

John Deere fuel pump is fixed, John Deere down again turns out the fuel injectors are bad, repaired and up and running again.

Material response: Removal

Resign:

Recommend new Chair: