#### Dozer

Machined worn bearing surface on drive line yoke Changed transmission fluid and filters

Replaced failed hydraulic return hose at radiator

Replaced parking brake cable and radiator cap

Purchased two batteries, 6 years of use

Engine oil & filter changes, replaced fuel filters, transmission & air filters as needed

#### Backhoe

Replaced two steering pump hydraulic hoses
Replaced two front left side loader bucket lift hoses
Welded fuel tank leak on left side pivot hub
Welded fatigue cracks on front bucket and loader arms

Engine oil & filter changes, replaced fuel filters, transmission & air filters as needed

### Water Truck

Installed new PTO water pump drive assembly and refurbished pump volute Replaced 3" inlet and 2 ½" discharge hoses, Serviced PTO drive shaft assembly Repairs to water tank leaks and replaced shim boards, welded pump mounting bracket Replaced broken head lamp and bezel adjusting screws Engine oil & filter changes, replaced fuel & air filters as needed

## **Dump Truck**

Replaced rear shocks

Replaced trunnion axle bearings and spacers, Torque leaf spring "U" bolt to 1200 foot pounds

Purchased four tires for rear axle

Replaced broken head lamp and right side marker light lenses

Replaced broken muffler mounting brackets

Engine oil & filter changes, replaced fuel & air filters as needed

### Service Truck

Purchased new battery, 3 years of use

Purchased four tires

Purchased fuel transfer pump and repaired tank leaks

Engine oil & filter changes, air filter replacements

### Road Material Processing

Over 500 cubic yards of sand, gravels and clays screened for road material mix Over 1000 cubic yards of pond materials excavated from the duck pond Approximately 125 dump truck loads of road mix placed on the roads

# **Additional Information**

Pushed up brush pile as needed and assisted in burning of brush pile
Pressure wash equipment monthly to maintain clean and proper operating conditions
Replaced faulty check valves on windmill pump for dip tank
Installed new pump house and pump controller at community well
Purchase approved for a 1750 gallon poly water tank to upgrade the community water holding tank
New water level float switch, wiring and support lumber scheduled to be replaced
Purchased PTO driven cement mixer attachment for the John Deere
Sold F800 dump truck

Sincerely,

Janette Winters, Road Committee Chairman Darell Fellers, Road Maintenance Operator