

Road Committee Report

05/16/2022 thru 06/11/2022

Road Work Completed

Worked Colleen Canyon from 300 to 312

- Dozer work to break up rocky roadbed
- Rock hammer work to remove embedded rocks
- Rock crusher work to process windrows to build roadbed
- Limbed trees and hauled 2 loads of brush to burn pile
- Hauled and placed 2 loads of road fill mix to build up roadbed at 310
- Hauled and placed 2 loads of road mix to cover road fill at 310

Equipment Repairs & Maintenance

580K Backhoe

- In shop for repairs. Hydraulic pump and parts have arrived to finish the repairs
- Cleaned hydraulic pump screen, inspected all components and order new filters

850C Dozer

- In shop for repairs. The dozer blade has been disassembled for repair of the main pivot pin and bushings. The leveling beam is in Alpine for machine shop work to rebuild main pin pivot bushings and worn down surfaces.
- Blade tilt cylinder is being rebuilt with new packing kit
- The dozer blade is being welded to fix fracture cracks and build up worn surfaces
- Worn pins and bushings in the "C-frame" will be replaced as needed

Mack Dump Truck

- The dump bed hydraulic reservoir was removed, cleaned of debris and hose leaks repaired
- Filled with 20 gallons of new hydraulic fluid

John Deere 7420

- The forward/reverse shift control module has been ordered to replace faulty circuit board

Road Material Processing

- Reclaimed 8 loads of sand and silt from upper catch at Duck Pond
- Excavated 8 loads of clay from Limpia Canyon
- Processed 16 loads (200 cubic yards) of road materials to be made into road mix

Additional Information

- Pushed up brush pile
- We are currently working in (Section 1) on upper Colleen Canyon
- Tomahawk and the Main Road will be worked prior to the Annual Meeting
- Hammer work, Rock crushing and addition of materials will be addressed

Sincerely Submitted,
Road Committee Chairman