

# Road Committee Report

10/15/2018 thru 11/10/2018

## Working Section 5

Saddle Bags  
Cross Trails  
Broken Arrow

## Road Work Completed

High Lonesome from Cedar Trail to High Lonesome Turn Around

- Blade and Crush, Improved roadbed crown
- Repaired roadbed seep at 332 HL with crushed rock and fill
- Hauled 8 loads of road mix
- Built up water diversion mounds
- Trimmed limbs and hauled brush to pile

Cedar Trail Loop

- Repaired washed out sections as needed

Far View

- Passable at this time
- Needs water diversion mounds and fill mix

High Lonesome Switch Backs

- Blade and Crush
- Hauled 3 loads rock mix to crush
- Hauled 4 loads of clay mix to blend

## Equipment Repairs & Maintenance

John Deere 7420

- Ordered replacement cover for cab air filter

Dump Truck

- Replaced flat tire

## Road Material Processing

- Reclaimed sand and gravel materials at 203 High Lonesome creek crossing
- Hauled 20 loads of pond materials to staging area
- Screened 20 loads for road mix
- Approximately 700 cubic yards of clay materials in inventory

## Additional Information

- The fabrication of a seven inch pass through rock screen will size materials for the rock crusher increasing the product yield from the reclaimed pond materials. Recycled and donated 2" steel pipe will be used to build the screen.
- Pushed up brush pile
- Purchased a 14" Abrasive chop saw for cutting metal

Sincerely Submitted,  
Janette Winters