

Road Committee Report

8/16/2021 thru 9/11/2021

Road Work Completed

Worked Upper Limpia Canyon at 524 to repair utility truck ruts in road bed

Worked Main Road from highway 166 to Wofford's, Blade and watered

Worked High Meadow, Placed 6 loads of mix to fix switch backs and washouts

Worked Low Meadow, Placed 7 loads of mix to steep hill sections and washouts

Worked Bandolero water crossing at Six Shooter to repair road bed

Worked Upper Limpia Loop from Low Meadow to 607, Road repairs from utility truck ruts

Worked Tejano Loop from Limpia Canyon to Juniper Pass, Relocated dirt to cover rocky sections

Worked Thompson Trail from Tomahawk to Cross Trail

Worked Saddle Bag hill, Blade and watered

Worked Fair View, Trim and hauled 2 loads of limbs to bush pile

Worked High Lonesome from Cedar Trail to 333 High Lonesome, Crusher and 4 loads of limbs

Worked Cedar Trail from Cedar Trail Loop to 206 Cedar Trail

Equipment Repairs & Maintenance

Mack Truck

- Replaced lower radiator coolant reservoir
- Changed engine oil and both filters, Cleaned air filter and greased drive line

International Water Truck

- Repairs to water valve linkage, Drill and set new spring pin on valve shaft
- Adjusted pump mounting bracket, Fabricating anchor strap to hold pump in proper location
- Greased PTO shaft, pump bearings and drive line
- Repairing water leaks on tank and exhaust leak at muffler inlet
- Need to purchase replacement mirror assemblies, head lamps and mounting bezels

770D Motor Grader

- Purchased new tire to replace the oldest tire
- Replaced o-ring seal on rear tire to fix slow leak
- Rotated newer tires to the back of machine, put older tires on the front
- Flat tire on left rear. Side wall failure due to old age. Will need a replacement next week.

Shop Air Compressor

- Purchased start and run capacitors for the motor. Did not fix the problem. Motor 19yrs old.
- Purchased and installed a replacement motor. Need to replace the two single 30 amp circuit breakers with one double pole single throw breaker

Road Material Processing

- Relocated 60 cubic yards of clay from duck pond to screen for inventory
- Reclaimed 10 cubic yards of gravels from Yellow Knife creek crossing
- Processed 70 cubic yards of clay and gravels for road mix

Additional Information

- Pushed up brush pile as needed
- Replaced toilet flapper in office restroom, Installed sediment filters for both toilets

Sincerely Submitted,

The Road Committee Chairman