

## Road Committee Report

6/14/2021 thru 7/10/2021

### Road Work Completed

Worked Tomahawk from the community center to the Tomahawk cattle guard

Worked the Main Road from Tomahawk cattle guard to Highway 166

Emergency road repairs after 8 plus inches of heavy rain:

- Worked Squaw Valley to Gun Club and lower Bandolero crossing
- Worked Bandolero culvert bridge, Six Shooter crossing and lower Remington
- Worked Tomahawk Trail crossings, Saddle Bag to High Lonesome creek crossings
- Worked 108 Squaw Valley creek crossing
- Worked Winchester Pass crossing
- Worked Yellow Knife to Yellow Knife Court
- Worked Main Road to repair washouts, ruts and drainage. Set cones to flag hazards.
- Worked lower Tomahawk and Crazy Horse crossing. Surveyed Yellow Knife and Tejas.
- Worked Colleen Canyon from Tomahawk to Whiskey Run and upper creek crossings
- Worked Cochise from Limpia to upper Stagecoach. Filled ruts and cleaned culvert inlets.
- Worked Deer Run. Removed tree debris at culvert crossing
- Worked Tejano Loop from Limpia Canyon to Tejano Loop Court
- Worked Tejano Loop from Limpia Canyon to McGuire Ridge.
- Worked Tejano Canyon crossing
- Worked High Meadow to Low Meadow. Repairs on steep road sections and switchbacks.

### Equipment Repairs & Maintenance

770D Motor Grader

- Replaced right rear tire with spare. Sidewall cracked due to age of the tire.
- Price of a new tire is \$774 mounted
- Cost of a spare rim from Yellow House Machinery is \$2,302. Will continue to search for a better price.

410G Backhoe

- Random no start problem: Starter relay contacts are sticking or possibly a faulty power “shut-off” switch. Starter can be removed for inspection of relay contacts and switch bypassed to isolate the problem.
- Belt tension bearing is failing. Replacement is \$200

580K Backhoe

- Installed new brake hose assemblies on trans-axle housing

### Road Material Processing

- Reclaimed 100 plus cubic yards of creek gravels from culvert inlets and crossings
- Processed 50 cubic yards of gravel and clay mix for road base

### Additional Information

- Pushed up brush pile as needed
- Diesel fuel level is at 250 gallons. Will need to place an order in August.

Sincerely Submitted,  
The Road Committee and Crew