## Equipment Repairs & Maintenance

### Dozer

- Replaced brake cable
- Pressure wash

#### Maintainer

- Tightened loose hydraulic hoses
- Pressure wash

#### Backhoe

Removed front bucket pins, cleaned clogged grease ports

#### Water Truck

• Repaired rear leak on water tank

# **Road Material Processing**

- Hauled 10 loads of pond materials to staging area
- Screened 10 loads for road mix
- Approximately 900 cubic yards of clay materials in inventory

### **Additional Information**

- Pushed up brush pile ashes, extinguished remaining hot spots
- Culvert repair by Country Store, Fastened steel plate to cover hole, backfilled
- Formed and Poured concrete pad for community well pump house replacement
- Construct and install pump house on new pad
- Purchased 800 gallons of off-road Diesel
- Donated concrete culverts being scheduled for delivery by Glenn Bohenberger,
  Thank you

Sincerely Submitted,

Janette Winters