

Sheet1

DMPOA Road Report
01/14/17

Worked:

Main road from ranch house to 166.

Ship torque converter for core refund.

Remove 3 trees at duck pond to be able to remove and screen more material.

All spare time has been used to screen and mix material.

Equipment:

Small dump truck transmission is shot and needs brakes.

John Deere bucket lift bolts had to be replaced

Big dump truck hydro pump went out

Employs:

Ray Queen as permanent part time.