

# Road Committee Report

12/11/2017 Thru 1/12/2018

## Currently Working Section 2

High Meadow- Material hauling scheduled for next week

Skyline- Dozer ready for work, Haul materials as needed

Finish Limpia Canyon Trail and Work upper Limpia with Dozer as needed

Tony's Pass- Remove large rocks, Haul materials as needed

## Road Work:

Comanche Crest to culvert

Tomahawk- Set 2 loads of road mix at Colleen Creek crossing

Stagecoach- Set 2 loads of road mix on crest of Stagecoach

Low Meadow- Adjust pitch and drainage, Work rough spots as needed to Low Meadow Point, Prep for road mix application

Cochise & Stagecoach intersection, Clean out Stagecoach culvert inlet, Place reclaimed materials on road and over culvert

Low Meadow- Low Meadow Point to Limpia Canyon Trail, Set 4 loads of road mix hauled by Julian

Low Meadow- Limpia Loop to Skyline, Survey Skyline for Dozer work

Low Meadow- Skyline to 215 High Meadow, Survey High Meadow Point

215 High Meadow to Cochise Canyon, Set 3 loads of road mix hauled by Dale

Main Road- Highway 166 Entrance to Cattle guard at Tomahawk: Bladed, Hauled 11 loads of water and Rolled to compact

Low Meadow- Haul and Set 3 loads of road mix above Limpia Canyon Trail, 2 loads of water hauled by Dale

## Equipment Repairs:

Replaced tire on maintainer, Installed new on the right rear and rotated next oldest to right front

Weld ball hitch and gusset on JD 7420 hitch frame

Removed and cleaned fuel bowl on water pump engine, Replaced drafting hose, Install quick connect couplings

Replaced radiator hose on backhoe, added antifreeze as needed

Replaced oil cooler gasket on Dozer, Replaced cooler hoses, added antifreeze as needed

Replaced tire on maintainer, Installed new on the left rear and rotated next oldest to left front

## Equipment Maintenance:

Grease and check fluids on maintainer, Air up rear tires, Wash windows

Replaced in-line fuel filter and water separator filter on JD 7420

Ray powerwashed backhoe engine and exterior, Cleaned dirt and rock off top side of rock crusher

Blew out air filters on Dozer, Order a new set

Changed oil and filter on Dozer, Changed primary and secondary fuel filters and cleaned fuel sediment bowl

Fueled up Equipment, Check fluid levels, Grease as needed

## Personnel Training:

Instruct Dale on equipment operations of Backhoe, Dump Truck, Water Truck, Company Truck and Screening procedures

Instruct Dale and Ray on JD front bucket removal procedure

Instruct Dale and Ray on back blade connection and operation, Instruct Rock Crusher Hookup

**Road Material Processing:**

Dale: 7 loads of clay excavated, screened and hauled to staging area

Dale: 4 loads of creek sand & rock excavated and hauled to staging area

Ray: 8 loads clay & gravels screened and mixed for inventory pile

Ray: 22 loads of clay material excavated and hauled to staging area

Current Inventory: Clay- 220 yards, Sand/Gravels- 20 yards, Road Mix- 70 yards, Caliche- 55 yards

**Additional Information:**

Brush pile pushed up with Dozer

Bladed equipment parking area

Organized equipment parking arrangement and attachments

Reloacted lumber and assorted metal debris to storage yard behind round fire house, Thank you Dale and Ray

Cleaned up trash around exterior of shop, Weed-eated grass around building and fuel tanks, Thank you Dale and Ray

Clean shop, Haul trash to Dumpsters, Thank you Julian

Water truck drafting pump upgrade to 3" capacity, Improved rear spray nozzle configuration, Thank you Julian and Willis

Remove brush and stumps from clay pond reclamation area, Firewood is still available if anyone is in need

Made entries in Repair Log Book as needed, Checked filter inventory for upcoming equipment service

Replaced water faucet in shop

**Thank you for slowing down when passing the working equipment and personnel**

**It gives us time to move off of the road for safe passage**

Respectfully Submitted,

Jackie Edwards – Road Chairman

Cindy Davis

Road Committee Member