Equipment Repairs & Maintenance

Backhoe

- Welded fatigue cracks on front bucket
- Need to order steel plate to rebuild bucket heel edge
- Found leak on fuel tank. Tank needs to be drained and welded

Maintainer

• Installed new cutting edges and hardware, rotated tires, spare repaired

Dozer

- Oil and Filter changed, tightened belly pan bolts, check for leaks
- Need new lip seal on fuel distributer
- Need to replace water pump bearings soon.

Water Truck

Oil and Filter changed

Dump Truck

• Sent front right tire in for repair, Leaking valve stem replaced

John Deere

- Locate bad injector, found seal leak causing poor performance
- Drained fuel tank, Replaced fuel filters, Oil and Filter change
- Found oil leak on oil cooler, O-ring needs to be replaced

Road Material Processing

· Reclaimed excess materials and relocated as needed

Additional Information

- Pushed up brush pile for scheduled burn
- Transported 55 gallon drum of motor oil from Alpine
- Ordered replacement fuel transfer pump for service truck diesel tank
- Shop organization, Cleaned up spare tire storage area and checked filter inventory
- The Duck Pond is now 80% full from recent rains

Sincerely Submitted, Janette Winters