

# Road Committee Report

4/16/2018 Thru 5/19/2018

## Section 4

Bandolero Trail  
Apache Trail  
Skull Rock Trail  
Broken Spoke  
Victoria Point  
Remington Ridge

### Road Work Completed:

Bandolero from Winchester Pass to Apache Mountain, 4 loads mix, 2 loads water  
Skyline from 116 to turn around, 3 loads mix  
Main Road from 166 to the Fire Station, Equipment and water provided by Texas Forest Service in case of Evacuation  
Bandolero from Apache Mountain to Broken Spoke, 3 loads mix, 1 load water, built water diverter at Twin Ponds  
Broken Spoke from Bandolero to Victoria Point, 4 loads mix, 2 loads water  
Bandolero from Broken Spoke to Chancellor Canyon, 5 loads mix, 2 loads water  
Chancellor Canyon from Bandolero to the turn around, 2 loads mix, 1 load water  
Six Shooter to 108 Remington Ridge, 2 loads mix, 1 load water  
Six Shooter to Apache Mountain, 3 loads mix, 2 loads water  
Panther Run from Stagecoach to 114 Panther Run, 1 load water

### Equipment Repairs:

JD7420, Replaced front axle bushings, pivot pins and repaired worn eye loop, ordered drive line yoke  
JD7420, Rebuilt selective control valves 1 & 2 with new o-rings and replaced #1 stepper motor.  
Dozer, Tightened loose muffler mounting bracket  
Dozer, Tightened loose oil pressure fitting at gauge  
Materials Screen, Replaced mounting brackets and tightened all hardware  
Maintainer, Installed new cutting edges, bolts and nuts

### Equipment Maintenance:

Grease equipment and maintain fluid levels  
Wash equipment to keep clean and monitor any leaks  
Dump Truck, Serviced batteries, cleaned terminal posts and checked voltages with tester

### Personnel Training:

Demonstrate Dozer controls and Operations to start and drive equipment

### Road Material Processing:

Excavated and hauled 15 loads of sand & gravel from Limpia Creek and Duck Pond  
Excavated and hauled 20 loads of pond dirt to staging area  
Excavated for Inventory 150+ cubic yards of clay from Duck Pond, Thank you Julain  
Processed 25 loads of materials for road mix, 24 loads applied to the roads  
Current Inventory: Road Mix- 10 cubic yards, Clay- 200+ cubic yards, Sand/Gravels- 20 cubic yards, Caliche- 20+ cubic yards

**Additional Information:**

Road Crew and members assisted with the McDannel Fire as needed, Thank you  
Stored water resources are being monitored during our extreme hazardous fire season  
Pushed up brush pile

**Please Drive with Care**

Respectfully Submitted,

Jackie Edwards, Road Committee Chairman  
Cindy Davis, Road Committee Member